

Model: OROBICO GRIGIO NATURE 120X120 (6)(A)

Codes: 100311864

Absorption: Bla - Porcelanico (E<=0.1%)



 Sistema DAP®
Declaración Ambiental de
Productos de Construcción

DIMENSIONAL FEATURES UNE-EN ISO 10545-2

Length	1200 MM	
Thickness	6 MM	
Width	1200 MM	
Length and width deviation	Below 0.15%	+/-0.3%*
Side straightness deviation	Below 0.15%	+/-0.3%*
Squareness deviation	Below 0.15%	+/-0.3%*
Surface flatness deviation	Below 0.15%	+/-0.4%*

*ISO-13006:2015 UNE-EN 14411:2017

MECHANICAL FEATURES UNE-EN ISO 10545-4-6-7-11

Abrasion resistance	<140
---------------------	------

*ISO-13006:2015 UNE-EN 14411:2017

HYGIENIC FEATURES UNE-EN ISO 10545-13-14

Chemical resistance	CLASE A
Stain resistance	5
Resistance to cold food products	APTO
Resistance to hot food products	APTO
Fastness to rubbing	APTO
Dimensional stability at elevated temperature	CUMPLE
Climate shock test. resistance index	RESISTE
Resistance to thermal shock	RESISTE
Flammability	A1

*ISO-13006:2015 UNE-EN 14411:2017

System Certification



Do not use cleaning agents containing hydrofluoric acid.

It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint.

For big sizes, it is recommended to fix with mortars containing polymeric additives and to use the double glueing technique.

Mosaic tiles must be grouted.

This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.

ANTI-SLIP VALUE

CEN/TS 41901/02, DIN-51130 y ASTM A137.1

Dynamic coefficient of friction	>0.42
Slip resistance (pendulum-wet)	CL1
Slip resistance (ramp)	R9-A
Resistance to bacteria	APTO
Resistance to cleaning products	APTO
Resistance to bathroom cleaning products	APTO
Resistance to cigarette burns	APTO
4s	DRY>36-LOW_WET>24-MOD.
Slip resistance (pendulum-dry)	>65

*ISO-13006:2015 UNE-EN 14411:2017

SCOPE OF USE

Technical code-1	Use on heavy traffic floors
Technical code-2	Dry interior floors

PACKING

Sales units per box	2.88 M2/BOX
Sales units per pallet	74.88 M2/PAL
Sales units per unit	1.44 M2/PIECE

System Certification



Do not use cleaning agents containing hydrofluoric acid.

It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint.

For big sizes, it is recommended to fix with mortars containing polymeric additives and to use the double glueing technique.

Mosaic tiles must be grouted.

This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.